


A7 power supply without filament Xfmr has dropper resistor for filaments
 A12 Power supply with 115V/6.3V filaments xfmr

- Pin on module connector
- Testpoint
- Pin on 32-pole main plug



Collins 344B-1 Instrumentation Unit

6 jan 2014 kb